

LDWSE  
4.8.1  
2/13/14


**Sanga, Ravi**

**From:** Dyer, Miles [mdyer@JorgensenForge.com]  
**Sent:** Thursday, February 13, 2014 9:00 AM  
**To:** Sanga, Ravi; Timothy.L.Westscott@USCG.mil  
**Cc:** 'Ernst, William D' (william.d.ernst@boeing.com) (william.d.ernst@boeing.com)  
(william.d.ernst@boeing.com)  
**Subject:** Update Drawing  
**Attachments:** 2014-02-12-13092-S1\_1-OPT 1.pdf

During the pre-construction meeting on 10 February, coffer dam corner designated as A-1 required a half sheet steel to be installed on the north-west wall which creates the corner to the wall running in a north-south direction.

A full sheet steel section will be used instead of the half sheet on the north-west wall. The full sheet installation will extend the length of the north wall approximately 10-12 inches. This area, inside the coffer dam; is annotated as an area where dredging is not required. There is no impact for future work to be performed during August 2014.

Miles Dyer  
Director, Environmental Programs



Jorgensen Forge Corporation  
8531 East Marginal Way South  
Seattle, Washington 98108  
Office Ph#: (206) 965-1352  
Mobile: (740) 777-7808  
Fax: (206) 357-1071  
[mdyer@jorgensenforge.com](mailto:mdyer@jorgensenforge.com)

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*


This Email message contained an attachment named  
image001.jpg  
which may be a computer program. This attached computer program could  
contain a computer virus which could cause harm to EPA's computers,  
network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced  
into the EPA network. EPA is deleting all computer program attachments  
sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you  
should contact the sender and request that they rename the file name  
extension and resend the Email with the renamed attachment. After  
receiving the revised Email, containing the renamed attachment, you can  
rename the file extension to its correct name.

For further information, please contact the EPA Call Center at  
(866) 411-4EPA (4372). The TDD number is (866) 489-4900.

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*



SHEET PILING TABLE (OPTION 1)		
AZ 38 700N	147'-0" (52 PAIRS)	

NOTE: 2 PAIRS HAVE BEEN ADDED TO SHEET PILE COUNT FOR EXTRA STOCK.

SHEET PILE CONNECTOR SCHEDULE		
MARK	DESCRIPTION	QUANTITY
(C)	SKYLINE STEEL - C 14 "1 1/2"	4

REVISIONS

DATE	DESCRIPTION
06/27/14	1.0 SHEET ADDITION

PROJECT

**B&T ENGINEERS & ARCHITECTS, INC.**  
1800 1ST AVENUE, SUITE 100  
SEATTLE, WA 98101  
(206) 461-1111

PROJECT TITLE

**JORGENSEN FORGE FACILITY**  
**8531 EAST MARGINAL WAY**  
**SEATTLE, WA**

SHEET TITLE

**OPTION 1**  
**SHORING PLAN**

PROJECT

1300023

DATE

06/27/14

DRAWN

MM

CHECKED

JT

SHEET

1

SHEET

S1.1<sub>1</sub>

OF

1

PROJECT

1300023

DATE

06/27/14

DRAWN

MM

CHECKED

JT

SHEET

1

SHEET

S1.1<sub>1</sub>

OF

1

OPTION 1 - SHORING PLAN